



Наименование	Номинальный ток, А	Характеристика срабатывания расцепителя	Тип шины	Количество в упаковке, шт.		Артикул
				групповой	транспортной	
BA 47-60 1P 1A х-на C	1	C	1P PIN, FORK 100 A	12	180	MVA41-1-001-C
BA 47-60 1P 2A х-на C	2	C	1P PIN, FORK 100 A	12	180	MVA41-1-002-C
BA 47-60 1P 3A х-на C	3	C	1P PIN, FORK 100 A	12	180	MVA41-1-003-C
BA 47-60 1P 4A х-на C	4	C	1P PIN, FORK 100 A	12	180	MVA41-1-004-C
BA 47-60 1P 5A х-на C	5	C	1P PIN, FORK 100 A	12	180	MVA41-1-005-C
BA 47-60 1P 6A х-на C	6	C	1P PIN, FORK 100 A	12	180	MVA41-1-006-C
BA 47-60 1P 10A х-на C	10	C	1P PIN, FORK 100 A	12	180	MVA41-1-010-C
BA 47-60 1P 16A х-на C	16	C	1P PIN, FORK 100 A	12	180	MVA41-1-016-C
BA 47-60 1P 20A х-на C	20	C	1P PIN, FORK 100 A	12	180	MVA41-1-020-C
BA 47-60 1P 25A х-на C	25	C	1P PIN, FORK 100 A	12	180	MVA41-1-025-C
BA 47-60 1P 32A х-на C	32	C	1P PIN, FORK 100 A	12	180	MVA41-1-032-C
BA 47-60 1P 40A х-на C	40	C	1P PIN, FORK 100 A	12	180	MVA41-1-040-C
BA 47-60 1P 50A х-на C	50	C	1P PIN, FORK 100 A	12	180	MVA41-1-050-C
BA 47-60 1P 63A х-на C	63	C	1P PIN, FORK 100 A	12	180	MVA41-1-063-C



BA 47-60 2P 1A х-на C	1	C	2P PIN, FORK 100 A	6	90	MVA41-2-001-C
BA 47-60 2P 2A х-на C	2	C	2P PIN, FORK 100 A	6	90	MVA41-2-002-C
BA 47-60 2P 3A х-на C	3	C	2P PIN, FORK 100 A	6	90	MVA41-2-003-C
BA 47-60 2P 4A х-на C	4	C	2P PIN, FORK 100 A	6	90	MVA41-2-004-C
BA 47-60 2P 5A х-на C	5	C	2P PIN, FORK 100 A	6	90	MVA41-2-005-C
BA 47-60 2P 6A х-на C	6	C	2P PIN, FORK 100 A	6	90	MVA41-2-006-C
BA 47-60 2P 10A х-на C	10	C	2P PIN, FORK 100 A	6	90	MVA41-2-010-C
BA 47-60 2P 16A х-на C	16	C	2P PIN, FORK 100 A	6	90	MVA41-2-016-C
BA 47-60 2P 20A х-на C	20	C	2P PIN, FORK 100 A	6	90	MVA41-2-020-C
BA 47-60 2P 25A х-на C	25	C	2P PIN, FORK 100 A	6	90	MVA41-2-025-C
BA 47-60 2P 32A х-на C	32	C	2P PIN, FORK 100 A	6	90	MVA41-2-032-C
BA 47-60 2P 40A х-на C	40	C	2P PIN, FORK 100 A	6	90	MVA41-2-040-C
BA 47-60 2P 50A х-на C	50	C	2P PIN, FORK 100 A	6	90	MVA41-2-050-C
BA 47-60 2P 63A х-на C	63	C	2P PIN, FORK 100 A	6	90	MVA41-2-063-C



BA 47-60 3P 1A х-на C	1	C	3P PIN, FORK 100 A	4	60	MVA41-3-001-C
BA 47-60 3P 2A х-на C	2	C	3P PIN, FORK 100 A	4	60	MVA41-3-002-C
BA 47-60 3P 3A х-на C	3	C	3P PIN, FORK 100 A	4	60	MVA41-3-003-C
BA 47-60 3P 4A х-на C	4	C	3P PIN, FORK 100 A	4	60	MVA41-3-004-C
BA 47-60 3P 5A х-на C	5	C	3P PIN, FORK 100 A	4	60	MVA41-3-005-C
BA 47-60 3P 6A х-на C	6	C	3P PIN, FORK 100 A	4	60	MVA41-3-006-C
BA 47-60 3P 10A х-на C	10	C	3P PIN, FORK 100 A	4	60	MVA41-3-010-C
BA 47-60 3P 16A х-на C	16	C	3P PIN, FORK 100 A	4	60	MVA41-3-016-C
BA 47-60 3P 20A х-на C	20	C	3P PIN, FORK 100 A	4	60	MVA41-3-020-C
BA 47-60 3P 25A х-на C	25	C	3P PIN, FORK 100 A	4	60	MVA41-3-025-C
BA 47-60 3P 32A х-на C	32	C	3P PIN, FORK 100 A	4	60	MVA41-3-032-C
BA 47-60 3P 40A х-на C	40	C	3P PIN, FORK 100 A	4	60	MVA41-3-040-C
BA 47-60 3P 50A х-на C	50	C	3P PIN, FORK 100 A	4	60	MVA41-3-050-C
BA 47-60 3P 63A х-на C	63	C	3P PIN, FORK 100 A	4	60	MVA41-3-063-C



BA 47-60 4P 1A х-на C	1	C	4P PIN, FORK 100 A	3	45	MVA41-4-001-C
BA 47-60 4P 2A х-на C	2	C	4P PIN, FORK 100 A	3	45	MVA41-4-002-C
BA 47-60 4P 3A х-на C	3	C	4P PIN, FORK 100 A	3	45	MVA41-4-003-C
BA 47-60 4P 4A х-на C	4	C	4P PIN, FORK 100 A	3	45	MVA41-4-004-C
BA 47-60 4P 5A х-на C	5	C	4P PIN, FORK 100 A	3	45	MVA41-4-005-C
BA 47-60 4P 6A х-на C	6	C	4P PIN, FORK 100 A	3	45	MVA41-4-006-C
BA 47-60 4P 10A х-на C	10	C	4P PIN, FORK 100 A	3	45	MVA41-4-010-C
BA 47-60 4P 16A х-на C	16	C	4P PIN, FORK 100 A	3	45	MVA41-4-016-C
BA 47-60 4P 20A х-на C	20	C	4P PIN, FORK 100 A	3	45	MVA41-4-020-C
BA 47-60 4P 25A х-на C	25	C	4P PIN, FORK 100 A	3	45	MVA41-4-025-C
BA 47-60 4P 32A х-на C	32	C	4P PIN, FORK 100 A	3	45	MVA41-4-032-C
BA 47-60 4P 40A х-на C	40	C	4P PIN, FORK 100 A	3	45	MVA41-4-040-C
BA 47-60 4P 50A х-на C	50	C	4P PIN, FORK 100 A	3	45	MVA41-4-050-C
BA 47-60 4P 63A х-на C	63	C	4P PIN, FORK 100 A	3	45	MVA41-4-063-C