



| Наименование | Номинальный ток, А | Характеристика срабатывания расцепителя | Тип шины | Количество в упаковке, шт. | | Артикул |
|------------------------|--------------------|---|--------------------|----------------------------|--------------|---------------|
| | | | | групповой | транспортной | |
| BA 47-60 1P 1A х-на С | 1 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-001-C |
| BA 47-60 1P 2A х-на С | 2 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-002-C |
| BA 47-60 1P 3A х-на С | 3 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-003-C |
| BA 47-60 1P 4A х-на С | 4 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-004-C |
| BA 47-60 1P 5A х-на С | 5 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-005-C |
| BA 47-60 1P 6A х-на С | 6 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-006-C |
| BA 47-60 1P 10A х-на С | 10 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-010-C |
| BA 47-60 1P 16A х-на С | 16 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-016-C |
| BA 47-60 1P 20A х-на С | 20 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-020-C |
| BA 47-60 1P 25A х-на С | 25 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-025-C |
| BA 47-60 1P 32A х-на С | 32 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-032-C |
| BA 47-60 1P 40A х-на С | 40 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-040-C |
| BA 47-60 1P 50A х-на С | 50 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-050-C |
| BA 47-60 1P 63A х-на С | 63 | C | 1P PIN, FORK 100 A | 12 | 180 | MVA41-1-063-C |



| | | | | | | |
|------------------------|----|---|--------------------|---|----|---------------|
| BA 47-60 2P 1A х-на С | 1 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-001-C |
| BA 47-60 2P 2A х-на С | 2 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-002-C |
| BA 47-60 2P 3A х-на С | 3 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-003-C |
| BA 47-60 2P 4A х-на С | 4 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-004-C |
| BA 47-60 2P 5A х-на С | 5 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-005-C |
| BA 47-60 2P 6A х-на С | 6 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-006-C |
| BA 47-60 2P 10A х-на С | 10 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-010-C |
| BA 47-60 2P 16A х-на С | 16 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-016-C |
| BA 47-60 2P 20A х-на С | 20 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-020-C |
| BA 47-60 2P 25A х-на С | 25 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-025-C |
| BA 47-60 2P 32A х-на С | 32 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-032-C |
| BA 47-60 2P 40A х-на С | 40 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-040-C |
| BA 47-60 2P 50A х-на С | 50 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-050-C |
| BA 47-60 2P 63A х-на С | 63 | C | 2P PIN, FORK 100 A | 6 | 90 | MVA41-2-063-C |



| | | | | | | |
|------------------------|----|---|--------------------|---|----|---------------|
| BA 47-60 3P 1A х-на С | 1 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-001-C |
| BA 47-60 3P 2A х-на С | 2 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-002-C |
| BA 47-60 3P 3A х-на С | 3 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-003-C |
| BA 47-60 3P 4A х-на С | 4 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-004-C |
| BA 47-60 3P 5A х-на С | 5 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-005-C |
| BA 47-60 3P 6A х-на С | 6 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-006-C |
| BA 47-60 3P 10A х-на С | 10 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-010-C |
| BA 47-60 3P 16A х-на С | 16 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-016-C |
| BA 47-60 3P 20A х-на С | 20 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-020-C |
| BA 47-60 3P 25A х-на С | 25 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-025-C |
| BA 47-60 3P 32A х-на С | 32 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-032-C |
| BA 47-60 3P 40A х-на С | 40 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-040-C |
| BA 47-60 3P 50A х-на С | 50 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-050-C |
| BA 47-60 3P 63A х-на С | 63 | C | 3P PIN, FORK 100 A | 4 | 60 | MVA41-3-063-C |



| | | | | | | |
|------------------------|----|---|--------------------|---|----|---------------|
| BA 47-60 4P 1A х-на С | 1 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-001-C |
| BA 47-60 4P 2A х-на С | 2 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-002-C |
| BA 47-60 4P 3A х-на С | 3 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-003-C |
| BA 47-60 4P 4A х-на С | 4 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-004-C |
| BA 47-60 4P 5A х-на С | 5 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-005-C |
| BA 47-60 4P 6A х-на С | 6 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-006-C |
| BA 47-60 4P 10A х-на С | 10 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-010-C |
| BA 47-60 4P 16A х-на С | 16 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-016-C |
| BA 47-60 4P 20A х-на С | 20 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-020-C |
| BA 47-60 4P 25A х-на С | 25 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-025-C |
| BA 47-60 4P 32A х-на С | 32 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-032-C |
| BA 47-60 4P 40A х-на С | 40 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-040-C |
| BA 47-60 4P 50A х-на С | 50 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-050-C |
| BA 47-60 4P 63A х-на С | 63 | C | 4P PIN, FORK 100 A | 3 | 45 | MVA41-4-063-C |